SMITH

ASSEMBLY INSTRUCTIONS

SPØ1

DISCLAIMER

ENSURE THAT ALL STEPS ARE FOLLOWED IN THE CORRECT ORDER AND
THAT NO STEP IS LEFT OUT.
A MINIMUM OF TWO PEOPLE ARE REQUIRED FOR ASSEMBLY.

TO PREVENT ANY DAMAGE OF THE PRODUCT, DO NOT USE A BOX CUTTER,
KNIFE OR SHARP OBJECT TO OPEN THE BOXES.

DO NOT LIFT THE TABLE BY ITS TOP. IF YOU HAVE TO LIFT THE TABLE,
LIFT IT BY HOLDING ONTO THE METAL STRUCTURE.

SP∅1

## ASSEMBLY INSTRUCTIONS

SMITH TABLE WITH WOOD TOP

PACKAGING
PARTS

BOX WITH FRAME
AND TOP

BOX WITH LEGS

WOODEN TOP WITH
METAL FRAME WITH
WOODEN SIDES

LEG WITH METAL L,
SCREWS FOR ASSEMBLY

TOP DISASSEMBLY

PLACE THE FRAME WITH THE ALREADY ASSEMBLED TOP UPSIDE DOWN ONTO A SOFT AND CLEAN
SURFACE SUCH AS A BLANKET.

# SMITH TABLE WITH WOOD TOP

TOP DISASSEMBLY

UNSCREW THE TOP COMPLETELY AND SET ASIDE. THE TOP WILL BE REASSEMBLED AT THE END.

STRUCTURE ASSEMBLY

LOOSEN GENTLY ALL THE SCREWS WHICH FIX THE WOODEN SIDES ONTO THE METAL FRAME.
DO NOT UNSCREW THE WOODEN SIDES.

STRUCTURE ASSEMBLY

ON A BLANKET, TILT THE METAL FRAME ONTO THE SIDE AND PLACE ONE SET OF THE LEGS INTO POSITION. ENSURE THAT THE METAL L SITS CORRECTLY IN ITS POSITION.
FIX ONLY THE 3 SCREWS WHICH CONNECT THE WOODEN LEGS TO THE ENDS OF THE METAL FRAME.
REPEAT ON THE OTHER SIDE.
CHECK AND TIGHTEN THE INSERTED SCREWS.

SMITH TABLE WITH WOOD TOP

STRUCTURE ASSEMBLY

NOW INSERT THE SCREWS FIXING THE METAL L ONTO THE WOODEN SIDES AND TIGHTEN.
REPEAT THE STEP ON THE OTHER SIDE.

SMITH TABLE WITH WOOD TOP

STRUCTURE ASSEMBLY

TIGHTEN ALL THE SCREWS WHICH FIX THE WOODEN SIDES ONTO THE METAL FRAME.
MAKE SURE THAT ALL SCREWS ARE TIGHTENED.

WOOD TOP ASSEMBLY

PLACE THE TABLE TOP ON A BLANKET WITH THE UNDERSIDE FACING UP.
PLACE THE ASSEMBLED TABLE STRUCTURE ONTO THE WOODEN TOP AND GENTLY REASSEMBLE THE TOP WITH ALL SCREWS.
DO NOT OVER-TIGHTEN THE SCREWS.

SMITH TABLE

PLACE THE TABLE ON ITS LEGS, MAKING SURE THAT IT IS STABLE.
IF THE TABLE STRUCTURE IS MOVING TOO MUCH, RE-CHECK THAT ALL SCREWS ARE TIGHTENED
CORRECTLY.

# SP01

ASSEMBLY INSTRUCTIONS

SMITH TABLE WITH GLASS TOP

PACKAGING
PARTS

BOX WITH FRAME   WOODEN CRATE WITH GLAS TOP   BOX WITH LEGS

METAL FRAME WITH   SELF-ADHESIVE RUBBERS   LEG WITH METAL L,
WOODEN SIDES   SCREWS FOR ASSEMBLY

SMITH TABLE WITH GLASS TOP

STRUCTURE ASSEMBLY

PLACE THE FRAME UPSIDE DOWN ONTO A SOFT AND CLEAN SURFACE SUCH AS A BLANKET ON THE FLOOR.
GENTLY LOOSEN THE SCREWS WHICH FIX THE WOODEN SIDES ONTO THE METAL FRAME.
DO NOT UNSCREW THE WOODEN SIDES.

SMITH TABLE WITH GLASS TOP

STRUCTURE ASSEMBLY

ON A BLANKET, TILT THE METAL FRAME ONTO THE SIDE AND PLACE ONE SET OF THE LEGS INTO
POSITION. ENSURE THAT THE METAL L SITS CORRECTLY IN ITS POSITION.
FIX ONLY THE 3 SCREWS WHICH CONNECT THE WOODEN LEGS TO THE ENDS OF THE METAL FRAME.
REPEAT ON THE OTHER SIDE.
CHECK AND TIGHTEN THE INSERTED SCREWS.

SMITH TABLE WITH GLASS TOP

STRUCTURE ASSEMBLY

NOW INSERT THE SCREWS FIXING THE METAL L ONTO THE WOODEN SIDES AND TIGHTEN.
REPEAT THE STEP ON THE OTHER SIDE.

SMITH TABLE WITH GLASS TOP

STRUCTURE ASSEMBLY

TIGHTEN ALL THE SCREWS WHICH FIX THE WOODEN SIDES ONTO THE METAL FRAME.
MAKE SURE THAT ALL SCREWS ARE TIGHTENED.

SMITH TABLE WITH GLASS TOP

STRUCTURE ASSEMBLY

IF THE TABLE STRUCTURE IS MOVING TOO MUCH, RE-CHECK THAT ALL SCREWS ARE TIGHTENED CORRECTLY.

SMITH TABLE WITH GLASS TOP

GLAS TOP ASSEMBLY

INSIDE THE PACKAGING/ATTACHED TO THE GLASS TOP ARE SELF-ADHESIVE RUBBER PADS.
GLUE THE RUBBER PADS ONTO THE WOODEN STRUCTURE AS SHOWN ABOVE.

SMITH TABLE WITH GLASS TOP

GLAS TOP ASSEMBLY

PLACE THE GLASS TOP ONTO THE STRUCTURE.
THE TOP SHOULD HAVE A CONSISTENT 2MM SHADOW LINE ON ALL SIDES.

SMITH TABLE WITH GLASS TOP